




KOMPSAT Imagery Quality Report

- KOMPSAT-2, 3, 3A (June ~ July 2020) -

□ Quality of KOMPSAT-2, 3, 3A


Satellite	Location(Geometric)	MTF(Spatial)
 KOMPSAT-2	N/A	7.3%
 KOMPSAT-3	8.7m RMSE	9.0%
 KOMPSAT-3A	5.9m RMSE	12.7%

※ Above location (geometric) accuracy is a result processed with POD/PAD.


※ Above MTF values are measured with MTFC off.



KOMPSAT-3 Location Accuracy




KOMPSAT-3A Location Accuracy






KOMPSAT-2 MTF



※ No valid scenes were acquired from January to March.



KOMPSAT-3 MTF



KOMPSAT-3A MTF

